From: Mari Info <

Sent: Monday, November 21, 2022 4:24 PM

To: Alfie Whitbread <

Subject: Re: EICR information

Hi Alfie,

You will keep in contact with the Assessor or should I send him a list with the requirement(in case I need to send it, could you please let me know what are the requirements)?

Kind regards.

Mario



Alina Tiribejea RESTAURANT MANAGER INFO@MARIDELIDINING.COM

From: Alfie Whitbread

Sent: 21 November 2022 16:15

To: Mari Info <

Subject: RE: EICR information

Also, the outside Markie due to electrical cables going up the side and across the ceiling has not been risk assessed

Alfie Whitbread

Fire Safety Advisor

Kensington & Chelsea, Hammersmith & Fulham, Kingston & Richmond.

Fire Safety Regulation

London Fire Brigade

169 Union Street London SE1 OLL

E:

M

london-fire.gov.uk

----Original Message----From: Alfie Whitbread

```
Sent: 21 November 2022 16:04
To: Mari Info <i
Subject: RE: EICR information
Thank you.
Mario, just so you know. I have had a conversation with the fire risk assessor stating "he needs to confirm
the level of FIRE RESISTING construction between the restaurant and single private dwelling above".
The above is stated in my informal letter sent in October 2022.
Thanks
Alfie Whitbread
Fire Safety Advisor
Kensington & Chelsea, Hammersmith & Fulham, Kingston & Richmond.
Fire Safety Regulation
London Fire Brigade
169 Union Street London SE1 OLL
london-fire.gov.uk
-----Original Message-----
From: Mari Info <
Sent: 21 November 2022 15:36
To: Alfie Whitbread
Subject: Re: EICR information
<font color="red"> [EXTERNAL EMAIL] Do not click links or open attachments unless you are expecting
them, even if you know the sender
</font>|
Please let me know if you need anything else
Sent from my iPhone
> On 21 Nov 2022, at 15:21, Alfie Whitbread
```

```
> Thank you for sending me the fire risk assessment.
> I need to ask the fire risk assessor a couple of guestions.
> Do you have his contact number please?
> Thank you
> Alfie Whitbread
> Fire Safety Advisor
> Kensington & Chelsea, Hammersmith & Fulham, Kingston & Richmond.
> Fire Safety Regulation
> London Fire Brigade
> 169 Union Street London SE1 OLL
> london-fire.gov.uk<a href="https://ddec1-0-en-ctp.trendmicro.com:443/wis/clicktime/v1/query?">https://ddec1-0-en-ctp.trendmicro.com:443/wis/clicktime/v1/query?</a>
url=http%3a%2f%2fwww.london%2dfire.gov.uk.asp%2f%3futm%5fsource%3dlfbemail%26utm%5fmediu
m%3de%2dsignature%26utm%5fcampaign%3demailsignature&umid=f08a06de-13ce-4eed-94e9-
86ed73fb9d23&auth=a3b2bea13e72878efb3497dd4084f1dd641209fd-
728c34f18f15716aefb181d6cfba9b591fc19b13>
> [cid:image001.jpg@01D8FDBC.D52DFEF0]<a href="https://www.facebook.com/LondonFireBrigade">https://www.facebook.com/LondonFireBrigade</a>
[cid:image002.jpg@01D8FDBC.D52DFEF0]<a href="https://twitter.com/LondonFire">https://twitter.com/LondonFire</a>
[cid:image003.jpg@01D8FDBC.D52DFEF0]<a href="https://www.instagram.com/londonfirebrigade/">https://www.instagram.com/londonfirebrigade/</a>
> From: Mari Info
> Sent: 21 November 2022 15:10
> To: Alfie Whitbread <
> Subject: Re: EICR information
> [EXTERNAL EMAIL] Do not click links or open attachments unless you are expecting them, even if you
know the sender
>1
> Dear Alfie,
```

Page 3 of 9

```
> I hope you are doing well.
> Thank you for your support in this matter.
> Please find attached the requested document.
> Let me know if you require other information.
> Kind regards,
> Mariano
> [cid:image004.png@01D8FDBC.D52DFEF0]
> From: Alfie Whitbread <
fire.gov.uk>>
> Sent: 14 November 2022 08:49
> To: Mari Info <
> Subject: RE: EICR information
> Thank you
> Alfie Whitbread
> Fire Safety Advisor
> Kensington & Chelsea, Hammersmith & Fulham, Kingston & Richmond.
> Fire Safety Regulation
> London Fire Brigade
> 169 Union Street London SE1 OLL
> E: alfie.whitbread@london-fire.gov.uk<mailto:alfie.whitbread@london-fire.gov.uk>
```

```
> london-fire.gov.uk<https://ddec1-0-en-ctp.trendmicro.com:443/wis/clicktime/v1/query?
url=http%3a%2f%2fwww.london%2dfire.gov.uk.asp%2f%3futm%5fsource%3dlfbemail%26utm%5fmediu
m%3de%2dsignature%26utm%5fcampaign%3demailsignature&umid=4e5b4d9b-88f5-481d-993e-
c5e36cffae48&auth=a3b2bea13e72878efb3497dd4084f1dd641209fd-
1ab9d94924cf359993e6bc26a9287ee3b5dce30f>
> [cid:image001.jpg@01D8FDBC.D52DFEF0] < https://www.facebook.com/LondonFireBrigade>
[cid:image002.jpg@01D8FDBC.D52DFEF0]<a href="https://twitter.com/LondonFire">https://twitter.com/LondonFire</a>
[cid:image003.jpg@01D8FDBC.D52DFEF0]<a href="https://www.instagram.com/londonfirebrigade/">https://www.instagram.com/londonfirebrigade/</a>
> From: Mari Info <in
> Sent: 14 November 2022 08:22
> To: Alfie Whitbread
fire.gov.uk>>
> Subject: Fwd: EICR information
> [EXTERNAL EMAIL] Do not click links or open attachments unless you are expecting them, even if you
know the sender
> Dear Alfie.
> Please find below the answer from our EICR provider.
> Kind regards,
> Mariano
```

> Sent from my iPhone

```
> Begin forwarded message:
> From: Bogdan Les -
> Date: 11 November 2022 at 15:58:59 GMT
> To: Mari Info <
> Subject: Re: EICR information
> Hi the Item on page number 16 indeed doesn't not complies with the current 18 edition wiring
regulations however that doesn't not mean that's it's not safe
> There is RCD protection in place but just because the consumer unit it's old and made out of plastic it
doesn't meant that it's dangerous
> On the report itself as you could see it states that it's a C3 which's means that's its recommendation to
get it done it's not compulsory, because the Overall EICR Report it's satisfactory
> Thank you
> Bogdan
> Bogdan Les
> Managing director
> https://ddec1-0-en-ctp.trendmicro.com:443/wis/clicktime/v1/query?
url=www.exelonelectrics.co.uk&umid=f08a06de-13ce-4eed-94e9-
86ed73fb9d23&auth=a3b2bea13e72878efb3497dd4084f1dd641209fd
bb917e9c8ed225d1120a9cf00b523328638018e3<a href="http://www.exelonelectrics.co.uk%0d">http://www.exelonelectrics.co.uk%0d</a>
> EICR Electrical Report<a href="https://ddec1-0-en-ctp.trendmicro.com:443/wis/clicktime/v1/query?">https://ddec1-0-en-ctp.trendmicro.com:443/wis/clicktime/v1/query?</a>
url=https%3a%2f%2fwww.exelonelectrics.co.uk&umid=e455c7b2-f13e-47dc-ba50-
43e50e6e6a76&auth=a3b2bea13e72878efb3497dd4084f1dd641209fd
```

```
ctp.trendmicro.com:443/wis/clicktime/v1/query?
url=https%3a%2f%2fwww.exelonelectrics.co.uk&umid=e455c7b2-f13e-47dc-ba50-
43e50e6e6a76&auth=a3b2bea13e72878efb3497dd4084f1dd641209fd-
ctp.trendmicro.com:443/wis/clicktime/v1/query?
url=https%3a%2f%2fwww.exelonelectrics.co.uk&umid=e455c7b2-f13e-47dc-ba50-
43e50e6e6a76&auth=a3b2bea13e72878efb3497dd4084f1dd641209fd-
77ded28943ee0f64c6e74478d6ca11f329731b42> / Full or Partial Rewire< https://ddec1-0-en-
ctp.trendmicro.com:443/wis/clicktime/v1/query?
url=https%3a%2f%2fwww.exelonelectrics.co.uk&umid=e455c7b2-f13e-47dc-ba50-
43e50e6e6a76&auth=a3b2bea13e72878efb3497dd4084f1dd641209fd-
77ded28943ee0f64c6e74478d6ca11f329731b42>
> On 11 Nov 2022, at 15:23, Mari Info <
> Please find attached the answer of the fire brigade, in answer to our Electrical Certificate.
> "Thank you Mario.
> Please read the electrician's comments. Some work is required.
> Could you tell me when you will arrange for this work to take place? Please check page 16."
> Kind regards,
> Alina
```

```
> From: Bogdan Les < b
> Sent: 10 November 2022 20:53
> To: Mari Info <
> Subject: EICR information
> Hi good evening
> Following the EICR report that was carried out on Sunday the 6th/11/2022 At Mari deli dinner at 1A
Eyot Gardens
> I've written the following information regarding the EICR report
> Because Of the amount of appliances that was plug in and I was unable to carry out the following test
procedures
> R1+R2
> Insulation resistance
> Earth fault loop impedance
> These test procedures I was not able to carry them due to the reason they be stated above
> However because you had previous test reason I've taken the results from the previous certificates and
type in the new one
>
> That's what you've signed on the EICR report on Sunday
```

```
> Thank you
> Hope that helps
> Kind regards
> bogdan
> Bogdan Les
> Managing director
> https://ddec1-0-en-ctp.trendmicro.com:443/wis/clicktime/v1/query?
url=www.exelonelectrics.co.uk&umid=f08a06de-13ce-4eed-94e9-
86ed73fb9d23&auth=a3b2bea13e72878efb3497dd4084f1dd641209fd-
bb917e9c8ed225d1120a9cf00b523328638018e3<a href="http://www.exelonelectrics.co.uk%0d">http://www.exelonelectrics.co.uk%0d</a>
> EICR Electrical Report<a href="https://ddec1-0-en-ctp.trendmicro.com:443/wis/clicktime/v1/query?">https://ddec1-0-en-ctp.trendmicro.com:443/wis/clicktime/v1/query?</a>
url=https%3a%2f%2fwww.exelonelectrics.co.uk&umid=e455c7b2-f13e-47dc-ba50-
43e50e6e6a76&auth=a3b2bea13e72878efb3497dd4084f1dd641209fd-
ctp.trendmicro.com:443/wis/clicktime/v1/query?
url=https%3a%2f%2fwww.exelonelectrics.co.uk&umid=e455c7b2-f13e-47dc-ba50-
43e50e6e6a76&auth=a3b2bea13e72878efb3497dd4084f1dd641209fd-
77ded28943ee0f64c6e74478d6ca11f329731b42>/Central Heating Wiring System<a href="https://ddec1-0-en-
ctp.trendmicro.com:443/wis/clicktime/v1/query?
url=https%3a%2f%2fwww.exelonelectrics.co.uk&umid=e455c7b2-f13e-47dc-ba50-
43e50e6e6a76&auth=a3b2bea13e72878efb3497dd4084f1dd641209fd-
77ded28943ee0f64c6e74478d6ca11f329731b42> / Full or Partial Rewire<a href="https://ddec1-0-en-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-partial-
ctp.trendmicro.com:443/wis/clicktime/v1/query?
url=https%3a%2f%2fwww.exelonelectrics.co.uk&umid=e455c7b2-f13e-47dc-ba50-
43e50e6e6a76&auth=a3b2bea13e72878efb3497dd4084f1dd641209fd-
77ded28943ee0f64c6e74478d6ca11f329731b42>
```