Part	Building Name	Building Address	Design Standard	Floors	Year of completio	Height of Building (M)	Flats	Tenants C (Average)	sement r Sub sevel	FRA Risk Rating	Construction	EWS Cladding/Spandrel	EWS Fire Risk	FF Lifts	Ventilation	Riser System	Sprinkler System	Evac System	Internal Escape Staircases	External Secondary Excaps Staircases	No. Final Exits	Open Balcony Walkway	Subject to Regulator Investigation?	Fire Incidents In Last 5 Years	History of Fire Spread	Additional Characteristic Risk	FRAPT TIER (1-5)	FRAPT SCORE (0- 100)	Date Registered (BSR)	Date Registered (LPB)
Part	Jepson House	PEARSCROFT ROAD LONDON SW6 28Q		18 (17 floors have dwellings)	1964	53	67	188	No	Moderate	Concrete frame, floor and ceiling, infill brick and	Insulated panels to kitchen and bedroom windows.	Yes	No	POV	DRY	NO	NO	1	0	2	No	No	No	None		s (VERY LOW)	19		
Mathematical part	Norland House			25 (23 floors have dwellings)	1968	75	180	504	No	Moderate	DICK WAIN		No	No	POV & AGV	WET	FLATS YES	YES	2	0	3	No	No	No	None	Cladding replacement underway	s (VERY LOW)	12		
Mathematical part	Poynter House	Edward Woods Estate, Queensdale Crescent, London W11 4TA		25 (23 floors have dwellings)	1968	75	180	504	No	Moderate	Concrete frame, floor and ceiling, infill brick and block walls	Rockpanel / Rockshield Xireme 10mm panel EWI system	No	No	POV & AGV	WET	FLATS YES	YES	2	0	3	No	No	Yes	None	Cladding replacement underway	s (VERY LOW)	12		
Minima	Stebbing House			25 (23 floors have dwellings)	1968	75	180	504	No	Moderate			No	No	POV & AOV	WET	FLATS YES	YES	2	0	4	No	No	Yes	None	Cladding replacement underway	5 (VERY LOW)	12		
Mathematical part	Bush Court			19 (17 floors have dwellings)	1971	57.9	102	286	No	Moderate			Yes	No	POV	DRY	NO	YES	1	0	1	No	No	No	None	Spandrel removal pending	4 (LOW)	34		
Mathematical part		Charecroft Estate, Shepherd's Bush Green London W12 8PN								Moderate	Concrete frame, floor and ceiling, infill brick and	EPSOPS insulated panels to living room windows.									2									
Mathematical biolity of the properties of the		-				-	_		_	Moderate Moderate								_			2				XPS spandrels 6 levels	pending				
Mathematical Registration	Barton House	2 STEPHENDALE RD, FULHAM, LONDON SW6 2PD			1985	56.7	76	213	YES	Moderate	Concrete frame and panel construction	Yes, small ones to windows on staincase and on	No	No	POV	DRY	NO	NO	1	0	1	No	No	No	None		4 (LOW)	29		
Mathematical properties	Herbert Montson House	CLEM ATLEE COURT, FULHAM, LONDON SW6 78Z		17	1959	33	68	228	No	Moderate		None	No	No	POV	DRY	NO	NO	1	0	2	No	No	No	None		5 (VERY LOW)	21		
Mathematical properties Mathematical pro	Linacre Court	GREAT CHURCH LANE, HAMMERSMITH, LONDON WE BDF		18	1985	51.2	69	193	No	Moderate	Concrete frame, floor and ceiling, infill brick and block walls	None	No	Yes	POV	WET	NO	NO	1	0	2	No	No	No	None		5 (VERY LOW)	15		
Mathematical Registration	Muscal House 9-67								_	Moderate	render panels	None			POV & AOV			-			_						4 (LOW)	24		
Part		SWIS 20H							_	Moderate	construction							-			-									
Part		LILLIE ROAD, LONDON SW6 7RY HUGH GAITSKELL CLOSE, LONDON SW6 7TJ							_	woderate Moderate	construction Concrete frame							-												\vdash
Martine Mart	Churchward House			11	1972	33	88	246	No	Moderate	Concrete frame, floor and ceiling, infill brick and block walls, render panels under windows	None	No	No	POV	DRY	NO	NO	,	0	2	No	No	No	None	Shared concierge and maintenace with fairburn House				
Marchan Marc		QUEEN CAROLINE STREET, HAMMERSMITH,							_	Moderate	Concrete frame, floor and celling.	None	No					_			_					Interconnected deck between sides of hydridge. Interconnected deck				
Marchan Marc	Herrietta House 1-20		inst fine.	10	1955	27	20	56	No	Moderate	Concrete frame,			No	OPEN AIR / POV	DRY	NO	NO	1	0	2	YES	No	No	None					
Part	Deaborough House	245 NORTH END ROAD, LONDON W14 SUH	ede sugmont	10	1972	27	80	224	No	Moderate	infill brick and block walls, render panels under windows	None	No	No	POV	DRY	NO	NO	1	0	2	No	No	No	None					
Maria	Fairburn House	25 IVATT PLACE, HAMMERSMITH, LONDON W14 9LW	er IV Part 1, P	11	1972	33	88	246	No	Moderate	under windows	None	No	No	POV	DRY	NO	NO	1	0	2	No	No	No	None					
Maria		245 NORTH END ROAD, LONDON W14 SUH	ngs, Chap							Moderate	infill brick and block walls, render panels under windows	None	No																	
Marie Registration Marie R		William Church Estate, Scotts Road, London, W12 8HG	pingjo						_	Moderate Moderate		Suspected EPSOPS panels under windows to	Yes								_									
Properties Pro	Ashcroft Square Block D	ASHCROFT SQUARE, KING STREET, HAMMERSMITH, WS OYJ	The design	8 (6 dwelings)	1973	31.3	40	112	No	Moderate	Concrete frame		No	No	OPEN AIR	DRY	NO	NO	2 (Multiple)	0	2	YES	No	No	None					
Part	Barcley Close 61-105	61-106 BARCLAY CLOSE, CASSIDY RD,	data for 8		1988	21.6	46	130	No	Moderate	Concrete frame, floor and ceiling, infill brick and block walls.	None	No	No	POV	DRY	NO	NO	1	0	2	No	No	No	None					
Marke Mark	Michael Stewart House (Sheltered)		of basis		1974	24.5		291	No	Moderate	Concrete frame and panel construction	XPS panels under windows		No	POV	DRY		NO	-	_	-	No			None	SHELTERED BLOCK	5 (VERY LOW)	21		
No. Confession			968 Code							Moderate	floor and ceiling, infill brick walls										-									
State Control Contro			CP 3:16						_	Moderate	infill brick walls																			
2									-	Moderate	infill brick walls																			
1										Moderate	Concrete frame								,		1									
AMORE SAME SAME SAME SAME SAME SAME SAME SAM	1-32 Joanna House Left	QUEEN CAROLINE STREET, HAMMERSMITH, LONDON WE 9BT			1953	21.6	32	90	No	Moderate	block walls.	None	No	No	POV	DRY	NO	NO	1	- 1	1	No	No	No						
Particular Par		WEST KENSINGTON, LONDON W14 SPL								Moderate	Concrete frame																			
Marked Cope Facility Facili		ASHCROFT SQUARE, KING STREET, HAMMERSMITH, WE GYJ						_	_	Moderate	and panel construction							-												\vdash
Amount Column C									-+	Moderate		XPS panels under windows next to														GARAGES UNDER	40.000			\vdash
Composition of Comp										Moderate	block walls.	running through														UNDER FLATS	4(CON)	- 43		\vdash
March 1941 Property 1942				7					YES	Moderate	construction		No	No				NO	1	- 1	2					FED discharges directly to narrow staircase				
Composition		SUSSEX PLACE, LONDON, W6 9DZ		7				-		Moderate Moderate	Traditional Brick with concrete pillars, timber	None				NONE			1							FED discharges directly to narrow staircase FED discharges directly				
Part	College Court 43-56				1900	21	14	39	YES	Moderate	floors and coated plaster ceilings		No	No	WINDOWS		NO	NO			_			No	None					
WINDER WASHING WASHI		ST PETER'S GROVE							_	Moderate Moderate	Concrete frame and flores with	None				Dev		1			-					ELATS OVER TESCO				\vdash
No.		WE SAY								Moderate																				\vdash
Manage M					1950		48		No	Moderate	manufa	None		No	OPEN AIR / POV	DRY	NO	NO			4			No		nas aquoent				
ABOUT SQUARE, 4 (see 161) 127 2 123 4 0 120 No Modele Control branch State State S (NOS STREET, 4 (see 161) 127 2 77 1 4 0 120 No Modele Control branch State S (NOS STREET, 4 (see 161) 127 2 77 1 4 0 120 No Modele Control branch State S (NOS STREET, 4 (see 161) 127 2 77 1 4 0 120 No Modele Control branch State S (NOS STREET, 4 (see 161) 127 2 77 1 4 0 120 No Modele Control branch S (NOS STREET, 4 (see 161) 127 2 77 1 4 0 120 No Modele Control branch S (NOS STREET, 4 (see 161) 127 2 77 1 4 0 120 No Modele Control branch S (NOS STREET, 4 (see 161) 127 2 77 1 4 0 120 No Modele Control branch S (NOS STREET, 4 (see 161) 127 2 77 1 4 0 120 No Modele Control branch S (NOS STREET, 4 (see 161) 127 2 77 1 4 0 120 No Modele Control branch S (NOS STREET, 4 (see 161) 127 2 77 1 4 0 120 No Modele Control branch S (NOS STREET, 4 (see 161) 127 2 77 1 4 0 120 No Modele Control branch S (NOS STREET, 4 (see 161) 127 2 77 1 4 0 120 No Modele Control branch S (NOS STREET, 4 (see 161) 127 2 77 1 4 0 120 No Modele Control branch S (NOS STREET, 4 (see 161) 127 2 77 1 4 0 120 No Modele Control branch S (NOS STREET, 4 (see 161) 127 2 77 1 4 0 120 No Modele Control branch S (NOS STREET, 4 (see 161) 127 2 77 1 4 0 120 No Modele Control branch S (NOS STREET, 4 (see 161) 127 2 77 1 4 0 120 No Modele Control branch S (NOS STREET, 4 (see 161) 127 2 77 1 4 0 120 No Modele Control branch S (NOS STREET, 4 (see 161) 127 2 77 1 4 0 120 No Modele Control branch S (NOS STREET, 4 (see 161) 127 2 77 1 4 0 120 No Modele Control branch S (NOS STREET, 4 (see 161) 127 2 77 1 4 0 120 No Modele Control branch S (NOS STREET, 4 (see 161) 127 2 77 1 4 0 120 No Modele Control branch S (NOS STREET, 4 (see 161) 127 2 77 1 4 0 120 No Modele Control branch S (NOS STREET, 4 (see 161) 127 2 77 1 4 0 120 No Modele Control branch S (NOS STREET, 4 (see 161) 127 2 77 1 4 0 120 No Modele Control branch S (NOS STREET, 4 (see 161) 127 2 77 1 4 0 120 No Modele Control branch S (NOS STREET, 4 (see 161) 127 2 77 1 4 0 120 No Modele Control branch S (NOS STREET, 4 (see 161) 127								_	_	Moderate	panels Concrete frame with brick infill					DRY		-												
Macrost Equation Macrost Equ										Moderate	panels Concrete frame								,	-						FLATS OVER SHOPPING CENTER				
		KING STREET, HAMMERSMITH, WE GYJ			1973 1973	27.1	40			Moderate Moderate	and panel construction		No No	No No			NO NO	NO NO						No No		FLATS OVER SHOPPING CENTER FLATS OVER SHOPPING CENTER				

- 1. The number of high rise (above 18m) council housing tower blocks owned by your local authority 49
- 2. The number of council housing blocks you own of any height subject to the Regulatory Reform Fire Safety Order (blocks of two or more premises with common parts)

- 3. The number of individual flats contained in (1) and (2) (please provide separately)
 4. The number of blocks that have been fitted with sprinkler systems in answer to (1) and (2) (please provide separately)
 5. The number of blocks which have been fitted with a fire alarm system capable of sending an alert to the entire building in (1) and (2) (please provide separately)
- 6. The number of people with disabilities which would hinder their ability to escape who live in the buildings in answer to (1)
- 7. The number of Personal Emergency Evacuation Plans developed for residents in the answer to (6)

If one of these questions takes the request over the threshold for officer time spent, please answer the remaining questions separately.

Question	Answer	Notes
Q1	49	HRRBs
Q2	1494	From FRA schedule
Q3(a)	3003	HRRB flats
Q3(b)	?	All other buildings, flat numbers - Asset management?
Q4(a)	5	Sprinkler systems in HRRB
Q4(b)	?	Sprincommon areas?
Q5(a)	9	EAS installed in the high rise, all other AICO flat only.
Q5(b)	?	How many of the 1464 buildings requiring FRA have a fire panel system?
Q6	?	Housing Management
Q7	114	Virginia Helps

49	HRRB
23	6 floors
55	5 floor
344	4 floor
544	3 floor
321	2 floor
177	1 floor

1513	TOTAL

The Fire Risk Assessment Prioritisation Tool is designed solely for responsible persons (or persons acting on their behalf) and asks a series of weighted questions about their buildings. It is not intended for use by other individuals or organisations.

Upon completion, the Fire Risk Assessment Prioritisation Tool provides a priority rating to the responsible person for updating the fire risk assessment to include external walls

The Fire Risk Assessment Prioritisation Tool forms part of the package of risk-based guidance that if complied with may be considered as a responsible person undertaking appropriate steps towards establishing compliance with the FSO steps which will then need to reasonably followed by the fire risk of the relevant premises being assessed and adequate and appropriate mitigations being put in place.

The Fire Risk Assessment Prioritisation Tool will allocate buildings into five priority categories to help with the prioritisation of fire risk assessments;

Tier 1 - very high priority

Tier 2 – high priority

Tier 3 - medium priority

Tier 4 – low priority

Tier 5 - very low priority

Tier 1

You (the responsible person) should take immediate action to engage a competent professional and update the fire risk assessment for this building.

The Fire Sector Federation has made available guidance on how to select a suitable fire risk assessor. While fire and rescue authorities do not complete fire risk assessments, they may give responsible persons advice (upon request) about how to identify help. They should also be able to refer responsible persons to relevant guidance as well as give advice on general fire safety matters.

Tier 2

You (the responsible person) should take action as soon as practically possible to engage a competent professional and update the fire risk assessment for this building.

The Fire Sector Federation has made available guidance on how to select a suitable fire risk assessor. While fire and rescue authorities do not complete fire risk assessments, they may give responsible persons advice (upon request) about how to identify help. They should also be able to refer responsible persons to relevant guidance as well as give advice on general fire safety matters.

Tier 3

You (the responsible person) should update the fire risk assessment for this building when you able to do so. This includes appointing the services of a competent professional. However, competent professional are expected to prioritise buildings in Tiers 1 or 2 and therefore, it may take some time before a competent professional can be appointed for Tier 3 buildings.

The Fire Sector Federation has made available guidance on how to select a suitable fire risk assessor. While fire and rescue authorities do not complete fire risk assessments, they may give responsible persons advice (upon request) about how to identify help. They should also be able to refer responsible persons to relevant guidance as well as give advice on general fire safety matters.

Tier 4

You (the responsible person) may wish to bring forward the next review of the fire risk assessment (as already required under the FSO) in light of the prioritisation assessment to consider those duties in the FSO amended by the Fire Safety Act. If no additional risk is identified, this should be done when you next review their fire risk assessment.

Tier 5

You (the responsible person) should consider those duties in the FSO amended by the Fire Safety Act when you next review the fire risk assessment (as already required under the FSO).